

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: April 04, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Punch out grid on the 3rd floor
Punch out ceiling tile on 3rd floor
Punch out exit lights on 3rd floor

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

